

P/N KE-VACTEST

DRILLHEAD VACUUM TESTER ASSEMBLY



GAUGE AND
DONUT
ASSEMBLED

IF THE GAUGE POINTER
DOES NOT START AT ZERO,
LIFT THE EDGE OF THE
RUBBER PLUG AND VENT
THE INTERNAL PRESSURE

K&E TECHNICAL, INC
1432 HWY 37. S.
WEST FRANKFORT, IL 62896
PH. 618-932-2245
FAX 618-937-3200
www.ketechinc.com

CF1V-000A (J7605A)
VACUUM GAUGE



KE-VGD RUBBER DONUT